CALFED Water Quality Monitoring Meeting

Purpose: Provide input to Pat Coulston for development of a draft CALFED Water Quality Monitoring Plan for the Delta.

Where: SFEI, 180 Richmond Field Station, 13255 46th Street, Richmond, CA 94804

When: 1100-1330 on 30 April 1997 (Wednesday)

Agenda¹

1100-1110	Chris Foe	Introductions
1110-1140	Pat Coulston	Review Draft CALFED water quality Monitoring Plan
1140-1210	Bill Jennings	Elements of a successful Delta monitoring Plan
1210-1240	Bruce Thompson Sam Louma	Coordination with USGS and RMP activities in San Francisco Bay
1240-1310	Val Connor	Coordination with the Sacramento Valley Watershed monitoring Program
1310-1330		Group discussion (1) (1) (1) (2) (4) (4) (4)

¹Either brown bag or order out for lunch.

Im working H.

W Card H.

on barisher are ...

 $D = 0 \ 4 \ 3 \ 4 \ 1 \ 4$